Aviation Safety Investigation Report 199602326

Boeing Co B737 Boeing Co B737

25 July 1996

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

State: Date:	Sydney, Aerodro NSW Thursday 25 July 1033 hours	Inv Category:	v pe: Incident 4 EST		
Aircraft Manufacturer: Aircraft Model: Aircraft Registration:	Boeing Co 737-377 VH-CZE			Serial Number:	23657
Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination:	Air Transport Scheduled Nil Adelaide SA Sydney NSW	Domestic High Capac	vity Passenger		
Aircraft Manufacturer: Aircraft Model: Aircraft Registration:	Boeing Co 737-376 VH-TAK			Serial Number:	23485
Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination:	Air Transport Scheduled Nil Coolangatta Ql Sydney NSW	Domestic High Capac	city Passenger		

Approved for Release: Monday, October 14, 1996

A Boeing 737 (B737) aircraft was being radar vectored onto final approach to runway 16R at Sydney from a right base, whilst another B737 aircraft was already established on a straight-in approach from 4,000 ft to runway 16L. The aircraft being radar vectored was given an initial instruction to turn right onto 060 degrees and descend to 3,000 ft, followed by a further instruction to turn right onto 130 degrees to intercept the 16R localiser.

However, this instruction was given late, resulting in the aircraft passing through the runway 16R extended centerline at 3,500 ft, conflicting with the leading B737, already established on final to runway 16L. The crew of the following aircraft had the other aircraft in sight at all times. At their closest point, separation was reduced to 1.2 NM laterally and 700 ft vertically. Instructions were then issued to both aircraft to resolve the confliction.