Aviation Safety Investigation Report 199603981

Piper Aircraft Corp Seneca Piper Aircraft Corp Chieftain

04 December 1996

Aviation Safety Investigation Report 199603981

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199603981 Occurrence Type: Incident

Location: 6km S Moorabbin, Aerodrome

State: VIC Inv Category: 4

Date: Wednesday 04 December 1996

Time: 0720 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Manufacturer: Piper Aircraft Corp

Aircraft Model: PA-31-350

Aircraft Registration: VH-OZV Serial Number: 31-7405470

Type of Operation: Air Transport Passenger Scheduled

Damage to Aircraft: Nil

Departure Point:Moorabbin ViDeparture Time:0718 ESuTDestination:Devonport Tas

Aircraft Manufacturer: Piper Aircraft Corp

Aircraft Model: PA-34-200T

Aircraft Registration: VH-PWQ Serial Number: 3447028

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Nil

Departure Point: Berwick Vic

Departure Time:

Destination: Ballarat Vic

Approved for Release: Thursday, December 12, 1996

VH-OZV departed Moorabbin from runway 35L and after making a left turn, commenced tracking in a southerly direction on climb to 9,000 ft. Three miles south of Moorabbin the pilot called RAS but the aircraft was not identified because its transponder was not being interrogated. The RAS controller passed traffic information to the pilot of OZV on an aircraft two miles at 12 o'clock, also with no transponder return. The pilot of OZV sighted the other aircraft in his 11 o'clock position, 100 to 200 ft higher. He took evasive action, in the form of a left turn, to avoid a collision.

The conflicting aircraft was later identified as VH-PWQ, whose transponder suddenly started operating after traffic information was passed to OZV. The pilot of PWQ said that he flies from Berwick to Ballarat, as he was on this occasion, once a week, and transits via the coast south of Moorabbin at 2500 ft. He listens out on RAS and the appropriate Moorabbin tower frequency for traffic. However, he did not make a broadcast of his position, altitude and intentions on the Moorabbin tower frequency, as is required by AIP OPS 42.2.1. He heard OZV departing Moorabbin but never saw it, even when they pssed in close proximity.