Boeing Co B747

11 March 1995

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

199500695

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199500695 Occurrence Type: Incident

Location: Quarry

State: SA **Inv Category:**

Date: Saturday 11 March 1995

0740 hours Time Zone **CSuT** Time:

Highest Injury Level: None

Aircraft Boeing Co

Manufacturer:

Aircraft Model: 747-400

Aircraft Registration: G-BNLG Serial Number:

Type of Operation: Air Transport High Capacity International Passenger

Scheduled

Damage to Aircraft: Nil

Departure Point: Melbourne Vic **Departure Time:** 0649 CSuT **Destination:** Adelaide SA

Crew Details:

Hours on

Role	Class of Licence	Type Ho	urs Total
Pilot-In-Command	Foreign	500.0	14500

Approved for Release: Thursday, March 16, 1995

The aircraft was approaching Adelaide from Melbourne having received an airways clearance for descent to 3000ft, with a pilot's intercept of the runway 23 localizer.

Approximately 46km east of Adelaide the DME reading disappeared from the FMS CDU. The captain then selected the appropriate "FMS fix" page to reinsert the data which caused a "time out resynch" message to appear on the FMS CDU.

It was the crews first flight into Adelaide and a correct approach briefing had been given. Weather conditions were perfect, the wind calm with no cloud and unlimited visibility. The captain stated that due to the FMS problem, both he and the first officer, who was apparently hand flying the aircraft, had had a momentary lapse in monitoring the approach, and allowed the aircraft to pass through the localizer.

The first officer noticed the runways of an aerodrome immediately in front of them, notified Adelaide Approach that the aerodrome was in sight, and reacted instinctively by commencing a right turn for base leg to what he believed was runway 23, without descending below the cleared altitude of 3000ft.

The error was immediately recognised by the crew, at the same time Adelaide Approach advised "wrong aerodrome". The aircraft had been positioning for Parafield, a general aviation airport situated 20km north-east of Adelaide, and was then turned back onto the localizer for a landing on runway 23 at Adelaide.

The captain said that if weather conditions had been different he would not have spent time rectifying the DME fault, but would have completed the flight monitoring the navigation instruments to Adelaide via the 23 ILS. He is to submit an ASIR to his company on return to the United Kingdom, with a recommendation that Parafield and Edinburgh airports be highlighted on company operational documentation.