Aviation Safety Investigation Report 200000924

Agusta, SPA, Costruzioni Aeronautiche 47G-3B-1

16 March 2000

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number:	200000924	Occurrence Type:	Accident
Location:	13km N Casino		
State:	NSW	Inv Category:	4
Date:	Thursday 16 Mar	ch 2000	
Time:	0945 hours	Time Zone	ESuT
Highest Injury Level:	None		
Aircraft Manufacture Aircraft Model: Aircraft Registration: Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination:	47G-3B-1	Costruzioni Aeronautiche Aerial Agriculture - Other	Serial Number: 80342
Crew Details:			

	Hours on		
Role	Class of Licence	Type Hours Total	
Pilot-In-Command	Commercial	6000.0	15200

Approved for Release: Monday, March 27, 2000

After the interim completion of agricultural spraying operations, the property owner asked the pilot to disperse one load of insecticide over a neighbour's property. The adjacent property owner had requested this work to be done. As the pilot hover-taxied an Agusta-Bell 47G-3B1 helicopter towards a water replenishing point on the neighbour's property, the cockpit bubble and one main rotor blade of the helicopter struck an unseen single strand high-tension power line partially concealed by a shed. The pilot was able to maintain control of the helicopter and landed safely. The helicopter sustained minor wire impact damage to one main rotor blade, the main rotor mast, and one tail rotor blade. The pilot and passenger escaped without injury.

The water tanks were near a shed which partially concealed the wire which was at an angle of about 45 degrees to a height of 60 to 70 feet AGL. The wire also blended into the background foliage. The pilot had visited this section of the neighbour's property about 2 years ago. No wires were noted during this visit. The owner of the adjacent property had not briefed his neighbour to inform the pilot about a new wire that had been erected near the water tanks. Consequently, the pilot had not been adequately briefed by the other property owner as to the presence and location of the recently erected wire which was in close proximity to the water tanks.