**Aviation Safety Investigation Report 199802614** 

Piper Aircraft Corp Chieftain

**08 July 1998** 

## Aviation Safety Investigation Report 199802614

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199802614 Occurrence Type: Incident

**Location:** Young, Aerodrome

State: NSW Inv Category: 4

**Date:** Wednesday 08 July 1998

**Time:** 0603 hours **Time Zone** EST

Highest Injury Level: None

**Aircraft** Piper Aircraft Corp

**Manufacturer:** 

Aircraft Model: PA-31-350

Aircraft Registration: VH-XLB Serial 31-7852104

**Number:** 

**Type of Operation:** Air Transport Domestic Low Capacity Passenger

Scheduled

**Damage to Aircraft:** Nil

Departure Point:Young NSWDeparture Time:0603 ESTDestination:Cowra NSW

**Crew Details:** 

Hours on

Role	Class of Licence	Type Ho	ours Total
Pilot-In-Command	ATPL	1050.0	6989

**Approved for Release:** Wednesday, August 5, 1998

When the landing gear was selected up after takeoff, the right main landing gear failed to retract. The pilot in command then diverted to Cootamundra where a normal landing was carried out.

The investigation is continuing.