Aviation Safety Investigation Report 199702796

Boeing Co B737-400

27 August 1997

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number:	199702796	Occurrence Type:	Incident		
	60km SE Brisbane, Aerodrome	• •	• Inclucint		
	,		4		
State:	QLD	Inv Category:	4		
Date:	Wednesday 27 August 1997				
Time:	2025 hours	Time Zone	EST		
Highest Injury Level: None					
Aircraft	Boeing Co				
Manufacturer:					
Aircraft Model:	737-476				
Aircraft Registration:	VH-TJL			Serial	24437
				Number:	
Type of Operation:	Air Transport Domestic Hig	gh Capacity Passeng	er		
Damage to Aircraft:	Nil				
Departure Point:	Sydney NSW				
Departure Time:					
Destination:	Brisbane QLD				

Approved for Release: Tuesday, September 2, 1997

Circumstances

The aircraft was on descent towards Brisbane via Jacobs Well. The crew reported seeing glare from what they believed was a laset light east of the Brisbane - Gold Coast highway near the Gold Coast.

The light was not known to CASA. Consequently, there was no NOTAM concerning the light. CASA advised that it had also received a report concerning the light from a helicopter operator and intends to conduct a night flight to determine the position of the light and then proceed with NOTAM or other action as appropriate.