Aviation Safety Investigation Report 199303870

Partenavia Costruzioni Aeronautiche SPA P.68C

13 November 1993

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report 199303870

Occurrence Number:	199303870	Occurrence Ty	pe: Accident		
Location:	Corryong				
State:	VIC	Inv Category:	4		
Date:	Saturday 13 November 1993	5			
Time:	1500 hours	Time Zone	ESuT		
Highest Injury Level: None					
Aircraft Manufacture	r: Partenavia Costruzioni Ae	pronautiche SPA			
Aircraft Model:	P.68C				
Aircraft Registration:	VH-NAI	S	Serial Number: 286		
Type of Operation:	Instructional Dual				
Damage to Aircraft:	Substantial				
Departure Point:	Canberra ACT				
Departure Time:	1400 ESuT				
Destination:	Moorabbin VIC				

Crew Details:

	Hours on		
Role	Class of Licence	Туре Но	ırs Total
Pilot-In-Command	ATPL 1st Class	33.0	5800

Approved for Release: Wednesday, August 3, 1994

The aircraft was in cruise at an altitude of 8,000 ft. A sudden severe shower of hail was encountered, lasting about 5 seconds. Hail impact damage was sustained by the aircraft which continued the flight to Moorabbin.