Aviation Safety Investigation Report 199502756

SOCATA - Groupe Aerospatiale Tobago Lockheed Georgia Co Orion

17 August 1995

Aviation Safety Investigation Report 199502756

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199502756

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199502756 Occurrence Type: Incident

Location: 5km N Parafield, Aerodrome

State: SA **Inv Category:** 4

Date: Thursday 17 August 1995

Time: 1155 hours Time Zone **CST**

Highest Injury Level: None

Aircraft Manufacturer: SOCATA - Groupe Aerospatiale

Aircraft Model: TB-10

Aircraft Registration: VH-YHH **Serial Number:** 1590

Type of Operation: Instructional Solo

Damage to Aircraft: Nil

Departure Point: Murray Bridge SA

1120 CST **Departure Time: Destination:** Parafield SA

Aircraft Manufacturer: Lockheed Georgia Co

Aircraft Model: P-3C

Aircraft Registration: Serial Number:

Type of Operation: Non-commercial Other (including military)

Damage to Aircraft:

Departure Point: Edinburgh SA

Departure Time:

Destination: Edinburgh SA

Approved for Release: Tuesday, September 5, 1995

The student pilot was operating the last sector of a solo navigation exercise, tracking from Murray Bridge to Adelaide where a touch-and-go landing was made, before returning to Parafield at 1,500ft.

Parafield Tower cleared the aircraft for a straight-in approach to runway 03 L, with a clearance to land. The pilot reported on final at 1,500ft, but the aircraft was not initially sighted by the controller. It was then observed north west of the field, inside the RAAF Edinburgh Control Zone.

An Orion aircraft, conducting right hand circuits for runway 36 at Edinburgh, was on right base heading west when the other aircraft entered the control zone.

Radar plots revealed that VH-YHH passed behind the Orion at about the same level, with a horizontal separation of about 1000 metres.

