

**Aviation Safety Investigation Report
199300552**

**Boeing Co
B737-400**

24 February 1993

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199300552 **Occurrence Type:** Incident
Location: KAPNA
State: WA **Inv Category:** 4
Date: Wednesday 24 February 1993
Time: 1530 hours **Time Zone** UTC
Highest Injury Level: None

Aircraft Manufacturer: Boeing Co
Aircraft Model: 737-476
Aircraft Registration: VH-TJG **Serial Number:** 24432
Type of Operation: Air Transport High Capacity Passenger Scheduled
Damage to Aircraft: Nil
Departure Point: Sydney
Departure Time:
Destination: Perth

Approved for Release:

The crew of VH-TJG, enroute to Perth, made a position report at Kapna. The Melbourne air traffic controller was required to co-ordinate details of this report to the Perth Sector Two controller. This was not done. There was opposite direction traffic which could have come into conflict but there was no loss of separation.

