

**From:** s.47F(1)  
**To:** [ASIRFollowup](#)  
**Cc:** s.47F(1)  
**Subject:** Tyabb Searay crash s.47F(1) into Cessna 414 VH-PTA  
**Date:** Thursday, 26 November 2020 1:40:08 PM  
**Attachments:** [image001.png](#)  
[image002.png](#)  
[image003.png](#)  
[image004.png](#)  
**Importance:** High

---

Good afternoon ATSB,

Following my notification yesterday as the Peninsula Aeroclubs s.47F(1) in regards to the engine failure on take of s.47F(1) Searay and subsequent collision and impact with Cessna 414, please find attached images of the damage to both aircraft.


s.47F(1) On a basic examination of the Searay s.47F(1), it was identified that the fuel valve was in the off position. The on field engineers that completed the annual inspection the day prior removed the fuel bowls and they were found to contain only a minimal amount of fuel and not enough to sustain flight( Images attached).

The Peninsula Aeroclub with other locals have video footage which can be mailed to the ATSB on request due to the size of the files.

Any problems or concerns please revert.

Regards,

s.47F(1), s.22






---

**From:** s.47F(1) [redacted]  
**Sent:** Thursday, 26 November 2020 1:25 PM  
**To:** s.47F(1) [redacted]  
**Subject:** Crash

























Sent from my iPhone