**Aviation Safety Investigation Report 199901643** 

Cessna Aircraft Company Cutlass Cessna Aircraft Company Cessna Skyhawk

11 April 1999

## Aviation Safety Investigation Report 199901643

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

## **Aviation Safety Investigation Report**

199901643

Occurrence Number: 199901643 Occurrence Type: Incident

**Location:** Canberra, Aerodrome

State: **ACT Inv Category:** 4

Sunday 11 April 1999 Date:

1028 hours **Time Zone EST** Time:

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 172M

**Aircraft Registration:** VH-MGZ Serial Number: 17266694

**Type of Operation:** Non-commercial Pleasure/Travel

**Damage to Aircraft:** Nil

**Departure Point:** Canberra ACT

**Departure Time:** 

**Destination:** Tumut NSW

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 172RG

Aircraft Registration: VH-CSH Serial Number: 172RG0692

**Type of Operation:** Miscellaneous Unknown

**Damage to Aircraft:** Nil

**Departure Point:** Unknown

**Departure Time:** 

**Destination:** Canberra ACT

**Approved for Release:** Friday, April 16, 1999

The pilot of VH-MGZ was instructed to taxi for runway 30 and to hold short of runway 35. The aircraft was later observed approaching the holding point and taxiing at a considerable speed. The pilot was instructed to stop immediately. The aircraft came to a halt just within the flight strip of runway 35. VH-CSN was sent around from short final approach.

The pilot reported that he had been distracted by his preparation for a navigation exercise and by the two passengers on board his aircraft.